

MP2-chassis (Mono Plus 2)

ST2-chassis (Stereo 2)

ST2 is based on MP2 chassis with Stereo module.
Manufactured in Newcastle.

Chassis	Faults appeared in the colours	Possible cause of the fault
	Faults appeared in the picture	
		*
	Faults appeared in the sound	
		*
	No picture	
MP2	No picture during APSi (screen gets dark)	* CO47 (electronic fuse is active)
MP2 (18.3.99)	No picture, just noise, via Scart OK	* CD01 (TDA8362 pin 13)
	Other	
Note!	ST2 is based on MP2 chassis, added with Stereo module, so the hints concern both chassies.	