SW made in Turku 1998...

Dated	Chassis	Faults appeared in the colours	Possible cause of the fault
		Faults appeared in the picture	
		Faults appeared in the sound	
		No picture	
21.08.00	Mono F	No picture, led blinkd 4 times	* Check resistors R909, R913 and 922 (180k, 0W5, 1%)
			* Check capacitor C547, 20"/21" = 330p, 14" = 150p
			* Check screen grid voltage adjustment
		Other	